

DAILY MY 2006 Euro 4 (Trucks & Minibus)

SYSTEM	Operation	HOW	Notes
BODY NBC	Change configuration	By Teleservices	SW 2.34 SW 2.36 and SW 2.38 not available
	Diagnosis	By Easy Stand Alone	SW 2.34 SW 2.36 SW 2.38
	ECU Replacement(OLD readable)	By Easy Stand Alone	SW 2.34/2.36/2.38
	ECU Replacement(OLD Not readable)	By Teleservices	SW 2.34/2.36/2.38
	T22,T27,T28,T33	By Teleservices	4 different update by VIN Adjusts to the version SW NBC 2.31
	Adds key	By Easy Stand Alone	
	Plannig Maintenance	By Easy Stand Alone	
	Sw update	By Teleservices	SW -2.38
	Down Load SW	By Teleservices	SW 2.36 / SW 2.38
	Ecu Update	By Teleservices	Adjusts to the version SW NBC 2.38 the ECU <= 2.34
AIRBAG-NAB	Change configuration	By Teleservices	
	ECU Replacement	By Easy Stand Alone	
	Diagnosis	By Easy Stand Alone	
CLUSTER-NQS	ECU Replacement(OLD readable/not readable)	By Easy Stand Alone	
	Change configuration	By Teleservices	
	Diagnosis	By Easy Stand Alone	
	Change configuration	By Easy Stand Alone	
	New Ecu Programming DIS Download	By Teleservices	
	Injectors Recognition	By Easy Stand Alone	
	Diagnosis	By Easy Stand Alone	
ABS 8	Change configuration	By Easy Stand Alone	It is not possible to Fit the different Brake configuration in Network Ex Change to ABS 8 to ESP 8 NOT POSSIBLE
	Diagnosis	By Easy Stand Alone	
	ECU Replacement(OLD readable/not readable)	By Easy Stand Alone	
	Diagnosis	By Easy Stand Alone	
ABS +ASR 8	ECU Replacement(OLD readable/not readable)	By Easy Stand Alone	
ABS + ASR + ESP 8	Change configuration	By Easy Stand Alone	
AGILE GEARBOX	Change configuration	By Easy Stand Alone	UNTIL SW 6.8.2
	Diagnosis	By Easy Stand Alone	
	ECU Replacement (OLD readable/not readable)	By Easy Stand Alone	
Methane CNG 5SF MARELLIs	Change configuration	By Teleservices	
	ECU Replacement	By Teleservices	
	Diagnosis	By Easy Stand Alone	
	PTO	By Teleservices	for new ECU sw version 10 and 11
PARKING SENSORS	Diagnosis	By Easy Stand Alone	
Blue & Me	ECU Replacement	By Teleservices	Old ECU P.N. 69501294 New ECU P.N. 69503131
CONVERGE C1			
AIR CONDITION	Diagnosis	By Easy Stand Alone	
Heater Webasto	Diagnosis	By Easy Stand Alone	
TELMA MCR 18	Diagnosis	By Easy Stand Alone	
ECAS WABCO	Diagnosis	By Easy Stand Alone	
	Calibration	By Easy Stand Alone	