

STRALIS MY 2007 FACE LIFT

SYSTEM	Operation	HOW	Notes
BC2	Diagnosis	By Easy Stand Alone	SW 3.4 – 4.1
	Change configuration	By Teleservices	SW 3.4 – 4.1
	ECU Replacement(OLD readable/not readable)	By Teleservices	SW 3.4 - 4.1
	Programming	By Teleservices	SW 3.4 - 4.1
FFC - FRONT FRAME COMPUTER	ECU Replacement	By Easy Stand Alone	In BC2
	Diagnosis	By Easy Stand Alone	
Mux Module FFC RFC,PDM,DDM	Diagnosis	By Easy Stand Alone	FFC/RFC SW 21.X DDM / PDM SW 20.6
DENOX	Diagnosis	By Easy Stand Alone	
	SW Update	By Teleservices	Check with ECM DIS
	ECU Replacement(OLD readable)	By Easy Stand Alone/Teleservices	
	ECU Replacement(OLD Not readable)	By Teleservices	
	Replacement component	By Easy Stand Alone	
VCM	Change configuration	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	PTO	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Change configuration special OPTS	By Teleservices	FMS,EM...,Immobilizzer, Economy Power ... HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	ECU Replacement(OLD readable)	By Teleservices	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	ECU Replacement(OLD Not readable)	By Teleservices	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Storing new Keys on new ECU	By Teleservices	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Adds key	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Installation Allison gearbox in After Market	By Teleservices by automatic programming	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Diagnosis	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Change configuration	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
EM	PTO	By Easy Stand Alone	SW 1.2/1.3 /1.4
	ECU Replacement (OLD readable/not readable)	By Teleservices	SW 1.2/1.3/1.4
	Installation in After Market	By Teleservices by automatic programming	SW 1.2/1.3/1.4
	Diagnosis	By Easy Stand Alone	SW 1.2/1.3 /1.4
	PTO	By Easy Stand Alone	SW 1.2/1.3 /1.4
ECM	Diagnosis	By Easy Stand Alone	
	Change configuration	By Easy Stand Alone	
	ECU Replacement(OLD readable/not readable)	By Teleservices/Part Plant	
	Recognition Injectors	By Easy Stand Alone	
IC-CLUSTER	Diagnosis	By Easy Stand Alone	
	- Languages programming - - Replacement ECU	By Easy Stand Alone	SW 19.3/ 26.00