

EUROCARGO M.Y. 2008 Euro 4/5 (Trucks & Midirider/Medium bus)

SYSTEM	Operation	HOW	Notes
IBC3	Change configuration	By Teleservices	SW 4.00 SW 4.10
	Diagnosis	By Easy Stand Alone	
	ECU update SW 3.10/4.00--> SW 4.10	By Teleservices	
	ECU Replacement	By Teleservices	
Cluster (IC)	Change configuration	By Teleservices	SW 4.17 - 4.20
	ECU Replacement	By Teleservices	
	Diagnosis	By Easy Stand Alone	
ASTRONIC LITE	Diagnosis	By Easy Stand Alone	
	ECU Replacement	By Teleservices	
	Automatic Programming	By Teleservices	
VCM	Diagnosis	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	ECU Replacement	By Teleservices	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Change configuration special OPTS	By Teleservices	FMS,EM...,Immobilizzer ,,Economy Power ... HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	ECU Replacement (OLD readable/not readable)	By Teleservices	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Adds key	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Installation Allison gearbox in After Market	By Teleservices by automatic programming	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Diagnosis	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
	Change configuration	By Easy Stand Alone	HW2 (SW 6,5- 8,5) HW3 (SW 8,55)
EM	PTO	By Easy Stand Alone	SW 1.4
	ECU Replacement(OLD readable/not readable)	By Teleservices	SW 1.4
	Installation in After Market	By Teleservices by automatic programming	SW 1.4
	Diagnosis	By Easy Stand Alone	SW 1.4
ECM	Change configuration	By Easy Stand Alone	
	Diagnosis	By Easy Stand Alone	
	ECU Replacement(OLD readable/not readable)	By Teleservices/Part Plant	
	Recognition Injectors	By Easy Stand Alone	
ABS 6	Automatic Programming	By Teleservices	
	Diagnosis	By Easy stand alone	
	ECU Replacement	By Teleservices	With Programmino Card Ecus ABS/ASR and ABS/ASR/ESP